

# 2026 IREC

Got through max q but shredded ~12.5 seconds into flight due to inadequate tape holding shear pins and shear pins not being large enough to withstand aerodynamic separation forces.

---

Revision #3

Created 2026-06-26 23:37:14 UTC by Cooper Brown

Updated 2026-06-27 01:10:01 UTC by Cooper Brown