2025 Kansas

Folded due to not enough nose cone coupler engagement and a huge hole in the nose cone coupler

---

Revision #2
Created 2026-06-26 23:34:33 UTC by Cooper Brown
Updated 2026-06-26 23:35:48 UTC by Cooper Brown