2026 Kansas

Folded due to fin getting hit while removing motor from fincan, or from straight fold at the airbrake.

Revision #2
Created 2026-06-26 23:35:55 UTC by Cooper Brown
Updated 2026-06-26 23:36:44 UTC by Cooper Brown