

2025 Kansas

Folded due to not enough nose cone coupler engagement and a huge hole in the nose cone coupler

Revision #2

Created 2026-06-26 23:34:33 UTC by Cooper Brown

Updated 2026-06-26 23:35:48 UTC by Cooper Brown